SECOND CHECK

Each

Comment: SECOND CHECK

ENGINEERING **APPROVAL**



QC8

5.0

User: Jea	n-Luc Menard	Process SI	heet	
Customer:	CU-DAR001 Dart Helicopters Services	Draw	ring Name: HINGE	
Job Number:	43018		rt Number: D38143	
Job Number:		rdi	t rumper, 000140	
Seq. #:	Machine Or Operation:	:	Description :	
6.0	HAND FINISHING!	HAND FINISHING F	RESOURCE #1	1191
Comme	nt: HAND FINISHING RESOURCE #1	21/	ALREAL PRICE ALL DIE	11111
7.0	Chemical Conversion Coat as per QSI (POWDER COATING	POWDER COATING	08-10 1	31 (27)
	. A TANAN MATANAN MATANAN AND AND AND AND AND AND AND AND AND	0915	2	(2x)
Commer	nt: POWDER COATING		, , , , , , , , , , , , , , , , , , , ,	
	Powder Coat White Gloss (Ref. 4.3.5.1) ***MASK THREADED HOLE PRIOR TO	as per QSI 005 4.3 DPOWDER COAT***		
	() 2/	15=		
	START TIME: 8	0/	,	1 .
	FINISH TIME:	/	M-6-0	18/11/3/
6.0	CC3	INSPECT POWDER	COAT/CHEMICAL CONVERSION	0/10/
				β
	INSPECT POWDER COAT/CHEMICAL	CONVERSION	FJ 98	1/0/3/
9.0	PACKAGING 1	PACKAGING RESOU	RCE#1	713/21
		;		
Comment	PACKAGING RESOURCE #1 Identify and Stock		K 2 1	7
	Location:	h	20.31	
10.0	CC21	FINAL INSPECTIONA	V/O RELEASE	
		· :		
Comment:	FINAL INSPECTIONWIO RELEASE			
b Completion			121	
			11 00-31	
	·		FOSITIVE RECALL	
			EFFECTIVE DIW C8	AUTH
			RELEASED	DATE
		<u>:</u>		
		- :		

DART AEROSPACE LTD	•	Work Order:	43018
	40		
Description: HINGE		Part Number:	D 38 14-3
	2		
Inspection Dwg: D3814 , Rev:	A Chelum		Page 1 of #2

FIRST ARTICLE INSPECTION CHECKLIST

X First Article	Prototype	9
-----------------	-----------	---

Drawing Dimension	Tolerance	Actual Dimension	Accept	Rejest	Method of Inspection	Comments
3.30	+/030	3.301	V			
0.75	+/030	0.750	V			
0.13	+/030	0.127	/			• .
RO.25	+/030	RO.25	~		1	
RO.13	+/030	RO.13	/	i.		
4.00	+/~ 030	4.000	/			
RO,50	+1030	R 0.50				
0.50	+/030	0.501	<i>V</i>			
00.257	1.005/000	0.260				
1.00	+/030	1.001	ン .			
0.75	+/030	0.748	/			
0.05	+/030	0.050	\			41
1.00	+/030	0.997	V			
R 0.13	+/030	RO.13	✓			-
0.21	+/030	0.212				, <u>-</u>
1.05	+/030	1.05	~	·		
1.81	+/030	1.807	. レ			
0.13	+/030	0.126	· /			a 6
0.75	+/- 030	0.747				
RO-13	+/030	RO.13	-V			
0.10 x 45°	+/030	0.098 x45°	/		3	
0.05	+/ .030	0.050	V			÷
1350	+/- 1/20	135°		7		10

Measured by: A Audited by: Prototype Approval: Prototype Approval: Date: 08/10/30 Date: 08.1(.02.

Rev	Date	Change	Revised by	Approved
Α		New Issue	KJ/JLM	·

DART AEROSPACE LTD		1	Work Order:	43018
	٠.			
Description: HINGE		19.5	 Part Number:	D3814-3
	Ο	1		
Inspection Dwg: D3814 , Rev:	A Vrehm			Page 2 of 2

FIRST ARTICLE INSPECTION CHECKLIST

X First Article **Prototype**

Drawing Dimension	Tolerance	Actual Dimension	Accept	Rejest	Method of Inspection	Comments
0.13	+/030	0.127	/			
1.30	+/030	1.299	1			
1.50	+/030	1.500	/	<u> </u>		
			1	<u></u>		
				۸,	· 2	
			÷			
			:			
			1			
						1.
			:			•
			i i			,
				·		
					-··	<i>y</i> 2
	n.		-			,
				1		
		*				

Measured by: HA	Audited by:	Prototype Approval:	
Date: 08/10/30	Date:	Date:	

Rev	Date	Change		Revised by Approved
A	Date	New Issue		KJ/JLM

